

## BUILDING SAFETY CERTIFICATE

No. 3251 / 1110

Dated: 14/08/2023

Certified that the existing building ST. JOSEPH SCHOOL (name of the building or premises) at THUNAI, NADIGAWN, BAGESHWAR DIS-BAGESHWAR (address) comprised of 0.0 NO basement(s) and 3.0 NO (upper floors) owned/occupied by ST. JOSEPH SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.O. P.W.D. BAGESHWAR (Name of Department/ Govt.) on 14/08/2023 (date of inspection) in the presence of F.R VIJAY TELLIS, ST. JOSEPH SCHOOL (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes X (10th) (X/ XII) with effect from 14/08/2023 for a period of 2 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Due to minor crack and water logging in the roof of the building.
2. Water seepage observed in the class rooms of third floor.
3. Roof cleaning and crack filling with water proofing agent Required.
2. Building safety certificate needs to Re-certify in case of Building Extension.

Issued on 14/08/2023 at 5.00 P.M by

\* Strike out whichever is not applicable.

Signature with Seal

14/08/23

अभिजाती अभियन्ता

सन्दी खन्ड लोडि कि

(बागेश्वर)

Name: DIHAN SINGH KUTIYAL

Designation: EXECUTIVE ENGR.

Name & Address of Department/ Office: P.O. P.W.D. Bageshwar

(Assistant Engineer & above officer of concerned Govt. Department only)


**Note:** This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

\* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.


## प्रमाण पत्र

प्रमाणित किया जाता है कि कार्यालय जिलाधिकारी बागेश्वर के पत्रांक सं० 691/ (1)/ सत्ताईस-जे०ए०शि० विधिक/22 दिनांक 26.11.2022 के अनुपालन में आज दिनांक 07.12.2022 को ST. JOSEPH'S SCHOOL THUNAI, BAGESHWAR UTTARAKHAND का स्थल निरीक्षण किया गया उक्त पत्र के साथ संलग्न मानचित्र एवं ENGINEERS ENTERPRISES ARCHITECTURAL ENGINEERS/ CONSULTANTS APPROVED VALUERS, INTERIOR DESIGNING, PROJECT MANAGERMENTS P.C.F PLAZA-1 Bareilly Road Haldwani द्वारा दिये गये Structural Safety Certificate का अवलोकन किया गया, भवन चार मंजिला (Ground floor, First floor, Second floor & Third floor) में निर्मित है जिसमें हर मंजिल (floor) में एक-एक ब्लाक निर्मित है जो प्रथम दृष्टिया सामान्य परिस्थितियों में सुरक्षित प्रतीत होता है एवं नेशनल बिल्डिंग कोड ऑफ इण्डिया 2005 के मानकों के अनुरूप निर्मित है यदि भविष्य में विद्यालय द्वारा प्रस्तुत मानचित्र में किसी प्रकार का परिवर्तन किया जाता है तो यह प्रमाण पत्र स्वतः निरस्त समझा जायेगा।

संलग्न- (1) मानचित्र

  
07/12/2022

सहायक अभियन्ता  
प्रान्तीय खण्ड, लो०नि०वि०  
बागेश्वर।

  
07.12.2022

अधिशारी अभियन्ता  
प्रान्तीय खण्ड, लो०नि०वि०  
बागेश्वर।

  
MANAGER  
ST JOSEPH SCHOOL  
THUNAI, NADIGAON  
BAGESHWAR. U K 263642

  
PRINCIPAL  
ST JOSEPH SCHOOL  
THUNAI, NADIGAON  
BAGESHWAR. U K 263642